



RAIN TRACKER COLORS GIVEN AS BODY / STRIPE

NC = NO CONNECTION-- REMOVE FROM HARNESS

RESISTOR COLOR CODES:
68 = BLU-GRY-BLK

100 = BRN BLK BRN

IF 100 OHM NOT AVAILABLE, USE THESE THREE RESISTORS ALL IN PARALLEL:

220 = RED RED BRN

330 = ORN ORN BRN

390 = ORN WHT BRN

RAIN TRACKER INTERFACE WIRING DIAGRAM