



RAIN TRACKER COLORS
GIVEN AS BODY / STRIPE

NC = NO CONNECTION--
REMOVE FROM HARNESS

TEE INTO ALL WIRES AS SHOWN.
INSTALL EXTERNAL RESISTOR AS
SHOWN.

RAIN TRACKER INTERFACE WIRING DIAGRAM
WIPER SYSTEM CLASS:
XL-7 with RT-50